
## **APPENDIX A**

## **ENGINEERING APPENDIX FIGURES 151-200**

Jacksonville Harbor Navigation Study, Duval County, Florida

DRAFT
INTEGRATED GENERAL REEVALUATION
REPORT II AND SUPPLEMENTAL
ENVIRONMENTAL IMPACT STATEMENT



JACKSONVILLE, FLORIDA


CHECKED BY: DATED: MARCH 2013

**DREDGING CROSS SECTIONS** CUT-41 STATION 23+00 TO 25+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.






CHECKED BY: DATED: MARCH 2013

**DREDGING CROSS SECTIONS** CUT-41 STATION 26+00 TO 28+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.




JACKSONVILLE, FLORIDA

CHECKED BY: DATED: **MARCH 2013** 

DREDGING CROSS SECTIONS CUT-41 STATION 29+00 TO 31+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.




JACKSONVILLE, FLORIDA

CHECKED BY: DATED: **MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-41 STATION 32+00 TO CUT-42 STATION 1+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.






CHECKED BY: DATED: **MARCH 2013** 

**DREDGING CROSS SECTIONS CUT-42 STATION 2+00 TO 4+00** GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.






CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 5+00 TO 7+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

CHECKED BY: DATED:


**MARCH 2013** 

**CUT-42 STATION 8+00 TO 10+00** GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

**MARCH 2013** 

CUT-42 STATION 11+00 TO 13+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

**MARCH 2013** 

CUT-42 STATION 14+00 TO 16+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

159

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE SHORELINE SYMBOL IS NOT SHOWN.






CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 17+00 TO 19+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE SHORELINE SYMBOL IS NOT SHOWN.






CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 20+00 TO 22+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.






BTM CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 23+00 TO 25+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 26+00 TO 28+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.






CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 29+00 TO 31+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.






BTM CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 32+00 TO 34+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.






CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 35+00 TO 37+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.






CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 38+00 TO 40+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.






CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 41+00 TO 43+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.






CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 44+00 TO 46+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.






CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 47+00 TO 49+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.






втм CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 50+00 TO 52+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

втм CHECKED BY: DATED:


**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 53+00 TO 55+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

CHECKED BY: DATED:


**MARCH 2013** 

CUT-42 STATION 56+00 TO 58+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.





CHECKED BY: DATED:


**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 59+00 TO 61+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.





CHECKED BY: DATED:


**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 62+00 TO 64+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.






CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 65+00 TO 67+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

CHECKED BY: DATED:


**MARCH 2013** 

CUT-42 STATION 68+00 TO 70+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

CHECKED BY: DATED:


**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 71+00 TO 73+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.





CHECKED BY: DATED:


**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 74+00 TO 76+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

CHECKED BY: DATED:


**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 77+00 TO 79+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.






CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 80+00 TO 82+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.





CHECKED BY: DATED:


**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 83+00 TO 85+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 86+00 TO 88+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.






CHECKED BY: DATED:

**MARCH 2013** 

CUT-42 STATION 89+00 TO 91+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

**MARCH 2013** 

CUT-42 STATION 92+00 TO 94+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

**MARCH 2013** 

CUT-42 STATION 95+00 TO 97+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.




JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

DATED:

**MARCH 2013** 

CUT-42 STATION 98+00 TO 100+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

**MARCH 2013** 

CUT-42 STATION 101+00 TO 103+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 104+00 TO 106+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

**MARCH 2013** 

CUT-42 STATION 107+00 TO 109+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

**MARCH 2013** 

CUT-42 STATION 110+00 TO 112+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 113+00 TO 115+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.





CHECKED BY: DATED:


**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 116+00 TO 118+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

**MARCH 2013** 

CUT-42 STATION 119+00 TO 121+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

194

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE SHORELINE SYMBOL IS NOT SHOWN.





CHECKED BY: DATED:


**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 122+00 TO 124+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.






CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 125+00 TO 127+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

**MARCH 2013** 

CUT-42 STATION 128+00 TO 130+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.





CHECKED BY: DATED:


**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 131+00 TO 133+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

CHECKED BY: DATED:


**MARCH 2013** 

CUT-42 STATION 134+00 TO 136+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 137+00 TO 139+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.